



This Carolina Thomas Bus Buzz addresses a condition where the windshield wipers activate on their own.

Please make sure all the technicians in your county receive a copy of this.



Condition: The
Windshield Wipers
Activate on their own
periodically.

Carolina Thomas has
been working with the
manufacturer of this
switch to provide a
solution. That solution
is included here.





Buses built prior to July 18, 2011 will have the multifunction turn signal switch replaced with the latest part number (A06-36956-003) and a switch support bracket (06-83353-000) added.

Please see the attached Freightliner bulletin 54-9 for complete instructions. You can download this bulletin by going directly to our website at www.carolinathomas.com.

Click Carolina Thomas Bus Buzz. A .pdf file is here for your convenience.





Call us (800-440-3492)
or email us

(wcorder@carolinathomas.com) if you
have a bus with this condition
and we can get you the latest
multifunction turn signal
switch, bracket, and the
proper fasteners.

Note: You should not replace one of these
switches with an old part number. I.e. A06-
36956-000 or A06-36956-002.

