



**Buzz Here! Calling all NC  
County Transportation  
Service Technicians.**

**Subject: Fuel leak at fuel  
pump on Cummins ISB  
engines.**






**We are finding a fuel leak or fuel seepage on some units at the fuel pump area on Cummins ISB units.**

**This Carolina Thomas Bus Buzz shows you where to look and what to do if a repair is needed.**






Fuel pump

Fuel Manifold



Top View – Fuel Pump – Driver’s side of Engine



← Air Compressor  
← Fuel pump

Area to inspect for fuel leak or fuel seepage. Leak is usually on the bottom side.



**Bottom View of fuel pump from under bus – Driver’s side of Engine**



**If you discover fuel seepage in this area, we can assist you in getting you in touch with the closest authorized service center or Carolina Thomas can do the repair if needed in our shop.**

**Carolina Thomas is an authorized Cummins Service Center.  
Call Kerry (ext. 364) or Woody (ext. 383) at 1-800-440-3492.**

