




C2 Battery Box Tray Slides - Rollers Wearing Through The Slide.

This Carolina Thomas Bus Buzz is intended to just share information with you about something we learned from Cleveland County this week. Parts order history does not indicate it is a big issue but we wanted you to be looking for it to help us learn more so we can get it handled if it is going to be an issue in the future.





Area indicated is the where the roller rests on the battery tray slide when the box is closed. This photo shows the battery tray extended out for service.






Photo indicates tray slide roller that is wore completely through the battery tray slide. You can see roller pushed up through the slide in this photo. This photo shows the battery tray closed as if the bus was in operation.






Photo indicates tray slide roller that is in good condition and should allow the batteries to be pulled and serviced easily. This photo is also taken with the battery tray closed as if in operation.



C2 Battery Box Tray Slides

We need feedback from you on this. Please start watching your units and if we need to do something here for you please let us know. You can contact Woody Corder or Kerry Loggins as follows:

wcorder@carolinathomas.com or
kloggins@carolinathomas.com or call toll
free at 800-440-3492 and use extensions 383
and 364 respectively.

