

Fuel Tank Improvements

Complaint - Premature fuel tank corrosion

Correction

- Supplier process for prep and paint coating and coverage improved
- Supplier handling/shipping process improved to eliminate paint scratches
- Sump added to tank drain to prevent weld from “oil canning” causing leaks
- FCCC process for handling tanks during manufacturing improved by utilizing shop carts to eliminate scrapes/scratches of top coat causing future corrosion issues
- Drain slots added to mounting cage to aid in flushing out road debris
- Optional – Polyurea coating for additional corrosion protection





Improved std top coat



Drainage slots



Sump Drain

Optional - Polyurea coating

