

May 23, 2012

Carolina Thomas Bus Buzz # 87

Service Bulletin 54-14 on C2 Headlight Moisture



Dear Tom,

Carolina Thomas participates in a weekly conference call with members of DPI to discuss issues and progress on what we are working on. We recently discussed [moisture in the headlight assembly](#). Since more and more school personnel are reading our Carolina Thomas Bus Buzz information, we thought we would send out this [service bulletin 54-14](#) again. It covers the proper procedure for inspecting the light and what is acceptable, etc.

You have several options to access the bulletin. Every county has an Access Freightliner account or you can just click on one of the active links in the body of this email or you can go to www.carolinathomas.com and click the appropriate [Carolina Thomas Bus Buzz](#).

If you selected Carolina Thomas and a Thomas Built bus this year we are confident that you will receive the best bus built. We look forward to working for you to make sure you are satisfied. Our goal is to be the best bus vendor available in North Carolina. All [Carolina Thomas Bus Buzz](#) recipients were sent this newsletter. The latest "[buzz](#)" can always be located on our website at www.carolinathomas.com. And we can also be reached toll free at 1-800-440-3492.



Sincerely,

Buzz

Closing Headline

The Carolina Thomas Bus Buzz information can always be located by clicking this link <http://www.carolinathomas.com/CarolinaThomasBusBuzz.aspx>.
To view your subscription options, or opt out of this newsletter please [click here](#).

[Forward email](#)



This email was sent to tschaaf@carolinathomas.com by tschaaf@carolinathomas.com | [Update Profile/Email Address](#) | Rapid removal with [SafeUnsubscribe™](#) | [Privacy Policy](#).



Carolina Thomas, LLC | 6327 Burnt Poplar Road | Greensboro | NC | 27419